SI-210818 Service-Information Turbocharger



Electrical actuator cannot be taught-in or already generates an error with ignition ON

Introduction:

As for all turbochargers with electric actuators, the adaptive teach-in values in the engine control unit must be reseted. The teach-in procedure prescribed by the vehicle manufacturer must then be executed.


Note:

During the teach-in process, ensure that the voltage supply to the engine control unit is faultless. A weakening battery or corroded ground contacts on the engine or body can be the cause of deviations in the voltage supply. The electrical contacts of the harness-side plug must also be inspected.

Instructions:

Check <u>voltage supply</u> for actuator: Plug connector disconnected from actuator. Measurement on harness side. PIN 1 towards PIN 3, sowie PIN 1 towards GND = 5,0 Volt $\pm 0,2$ Check reference voltage, PIN 5 towards PIN 3 = 5,0 Volt $\pm 0,2$

Check signal voltage at actuator: (with suitable adapter cable). With ignition ON and engine running at idle speed. Signal voltage between PIN 5 and GND = 3,2 Volt $\pm 0,2$





 Vehicle Manufacturer: AUDI, VW, SKODA, SEAT
 Vehicle: A1, A3, Golf VII, Jetta IV, Passat, Scirocco, Tiguan, Kodiaq, Rapid, Superb II, Yeti, Leon, Leon SC, Leon ST, Toledo IV, 1.4 TSFI / 1.4 TSI
 Engine code: CMBA, CPVA, CXSA, CXSB, CZCA
 Validity: This service information is valid for renewing the turbocharger with
 BTS reference: T916665 BTS-Service-Set-Nr: T981462

 Bis-service-set-Nr:
 1981462

 OE-no.:
 04E145704F, 04E145704R, 04E145713N, 04E145721R

 Manufacturer part no.:
 49180-01230, 49180-01240, 49180-01270, 49180-01275

Please note: OE-references are only for means of comparison. The content of this Service Information is non-binding and is only for informational purposes. The manufacturer specifications have to be adhered to.