



# CAMSHAFT ADJUSTER PTA126-0042

## TECHNICAL INFORMATION FOR INSTALLATION

**It is instructed that the camshaft adjuster for the timing chain kit PTA114-0067 must be also replaced!**

For the dedicated cars it can happen that after assembly of a new camshaft adjuster and at the cold starting phase of the engine „rattling“ noises occur during start-up of the car in the environment of the engine.

A reason could be that the related oil control valve is polluted and was not replaced or that the oil control valve after assembly of the new camshaft adjuster was not readapted to the electronic control unit (ECU). But it is essential for a correct function of the new camshaft adjuster.

It could lead then to a so called „chain rattling“, which causes without fail an early wear (elongation!) of the timing chain as well as of the sprockets and of the chain tensioner.

In the worst case an engine damage can be arisen!

Furthermore it is recommendable that the electronic control unit (ECU) receives an update of the software after assembly of the camshaft adjuster.

