

Changed design and control of the electric actuator

Introduction:


The vehicle manufacturer has carried out during the production period technical changes to the electronic control of the electric actuator on the turbocharger.

Note:

The two turbochargers shown must not be reversed, even if the plug of the vehicle will fit on both turbochargers. Due to the different control of the actuator it comes to malfunction and damage the new turbocharger. A warranty is excluded by the manufacturer.

Instructions:

Before installing the new turbocharger you have to compare the design of the e-actuator with the old turbocharger.



Vehicle Manufacturer: Ford

Vehicle: Transit, Tourneo 2.2 TDCi

Validity: This service information is valid for renewing the turbocharger with

BTS reference: T916549, T917549

BTS-Service-Set-Nr: T981483, T981640

Please note: OE-references are only for means of comparison. The content of this Service Information is non-binding and is only for informational purposes. The manufacturer specifications have to be adhered to.