

INA Service Info

•

Tension pulley 531 0938 10

Always check that the tensioning direction is correct

Manufacturer: Geely, Volvo

Engines: 1.5 litre petrol

Part no.: 531 0938 10

For current listing refer to catalogue media

On engines manufactured by Geely and Volvo, tension pulley 531 0938 10 must be rotated in different directions to tension the toothed belt.

The tension pulley on engines manufactured by Geely must rotate in a clockwise direction, whereas on Volvo engines the tension pulley must rotate anti-clockwise.

If the set tensioning direction is incorrect, the toothed belt will not be correctly tensioned.



Figure: Tension pulley 531 0938 10

Please observe the vehicle manufacturer specifications!

