

A close-up photograph of a piston and cylinder head assembly. The piston crown is heavily coated with a dark, irregular layer of carbon deposits, which is a common sign of engine wear or improper combustion. The surrounding metal surfaces of the cylinder head and piston skirt appear relatively clean but show some signs of use.