

TECHNICAL**BULLETIN****TECH
MATE**

Bulletin Ref: TB21a

Mercedes A Class**AAL1118**

A charging issue on the Mercedes A Class CDI is often due to a fault with the ECU or 'SAM' control unit.

Both of these control units control and monitor the alternator charge output.

**TECH
MATE**

For further information on this or any other issue contact the Apec technical team by phone or email at:
Phone: 01174 288090 Email: technical@apecautomotive.co.uk

**FOLLOW US**

#TechMate | @TechMateAuto