

TECHNICAL

BULLETIN

**TECH
MATE**

Bulletin Ref: TB5a

AAL1702

Common issues for charging problems:

1. This unit is controlled by the vehicles ECU which can be defective.
2. A corroded B+ cable from alternator to the battery is also common issue.

**TECH
MATE**

For further information on this or any other issue contact the Apec technical team by phone or email at:
Phone: 01174 288090 Email: technical@apecautomotive.co.uk



FOLLOW US
#TechMate | @TechMateAuto