

Chevrolet Captiva

Vehicles equipped with stop/start system were subject to a main dealer recall in 2017.


'A risk of fire while driving due to thermal damage of the starter cable'

It is vital that this is checked and replaced if the starter motor connection has melted (Fig 1).



ASM1614







For further information on this or any other issue contact the Apec technical team by phone or email at: Phone: 01174 288090 Email: technical@apecautomotive.co.uk



FOLLOW US #TechMate | @TechMateAuto