

DRIVE.

FO304R DRIVESHAFT ASSEMBLY

Assembly

During the assembly of this Driveshaft, it is of HIGH IMPORTANCE that ALL BOLTS are TIGHTENED TO THE MANUFACTURERS RECOMMENDED TORQUE SETTINGS.

Failure to do so can result in damage to the Driveshaft and vehicle.



STEC.10017 25/07/22

