

Product info sh	eet	Robert	Bosch	0445020002
Special tools needed?	Yes	1.0001		
Fix crankshaft with locking				
	Pr	oduct speci	fic informa	ation
Programming	No			
Unlocking	No			
Adaption values reset	No			
Bleed	Yes	ignition on fo	r 30 seconds	
adjustment at mounting_1	No	Butter		
				<u> </u>
adjustment at mounting_2		1		
		Tightenir	ng torques	
Mounting fuelpump flange			5 Nm	1
Fuel connection			0 Nm	
High Pressure pipe nuts			0 Nm on pump,	27 Nm on rail
Pump pulley/sprocket			0 Nm	4.00
Tensioner timingbelt, -chain			0 Nm	
Bolt crankshaft			00 Nm	
		Accombly	inctruction	25
		Assembly	iiisti uctiol	15
Recommendation: replace	tuel filter			
Core charge terms:				
-externally intact,				
-no mechanical damage,				
-not dismantled,				
-no heavy corrosion.				