

## Monroe Technical Note 17

It may be necessary to slightly enlarge the hole in the lower suspension member to allow the shock absorber to pass through - DO NOT modify or file the shock absorber.