



KNOW HOW

TECHNICAL BULLETIN



NAL1796

Bulletin Ref: TB2n

This vehicle has a computer driven excitation circuit of the alternator regulator which takes data from the ambient temperature and engine load, a failed temperature sensor or broken wire to the regulator will result in a low charge voltage

Please double check before ordering and fitting.



Technical Support

Contact our expert technical team
on 03333 136597 or email
NAPATECHNICAL@allianceautomotive.co.uk



TechMate Support

Book a TechMate visit today!
Contact the team on 01174 288090
or email info@techmateteam.co.uk