



LuK Service Info
Part Nr. 500 1159 40
 Manufacturer: LANDINI



TB1538

Art.-Nr.: 500 1159 40

**Info: 500 1159 40 replaces / ersetzt / rem-
place / sustituye a / sostituisce 500 1159 10**



500 1159 10
OE 1423 473 M94



500 1159 40
OE 1423 473 M94

Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT