



LuK Service Info

Part Nr. 133 0272 10 – 330MM TBFR

Manufacturer: CNH

Model: 10, 40, 50, 5000, 6000, 7000, 8000 SERIES

Art.-Nr.: 133 0272 10



TB2078

**Info: 133 0272 10 replaces / ersetzt /
remplace / sustituye a / sostituisce
133 0004 50 & 133 0005 50**



633 3074 09 = 133 0272 10 + 332 0013 10

633 3135 10 = 133 0272 10 + 332 0013 10 + 500 0199 40 + 410 0021 00

633 1126 19 = 133 0272 10 + 333 0032 10

633 1130 17 = 133 0272 10 + 333 0032 10 + 500 0199 40 + 410 0021 00

633 3075 09 = 133 0272 10 + 333 0087 10

633 3075 10 = 133 0272 10 + 333 0087 10 + 500 0199 40 + 410 0021 00

633 1127 09 = 133 0272 10 + 333 0033 06

633 1131 07 = 133 0272 10 + 333 0033 06 + 500 0199 40 + 410 0021 00



When replacing a 4 lever coil spring clutch with LuK diaphragm type clutch, shims are not required.



Wenn die 4-Hebel-Schraubenfederkupplung durch eine LuK-Tellerfederkupplung ersetzt wird, entfallen die Segmentbleche.



Le remplacement d'un embrayage à ressorts hélicoïdaux à 4 leviers par un embrayage à diaphragme LuK ne requiert pas de cales de réglage.



Al reemplazar el embrague de muelles helicoidales con 4 patillas por el de diafragma no es necesario colocar calzos.



Quando si sostituisce una frizione a molle elicoidali a 4 leve con una frizione di tipo a diaframma LuK, non sono necessari distanziatori.

Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT



133 0004 50



133 0005 50



133 0272 10

