



Product Technical Info

TIMING BEL KIT - TBK5005.01

AVVERTENZE SUL CORRETTO MONTAGGIO	WARNING INSTRUCTIONS FOR A CORRECT ASSEMBLY
<p>Attenzione al montaggio del tenditore automatico contenuto nel kit in oggetto.</p> <p>I due dentini evidenziati dalle frecce (Fig.1), devono essere alloggiati fra due incavature presenti sul motore (Fig.2).</p> <p>Se non viene rispettata la corretta procedura di montaggio, è possibile sbagliare il posizionamento dei dentini con conseguente malfunzionamento della distribuzione ed eventuali danni al sistema.</p>	<p>Pay attention to the assembly of the automatic tensioner contained in the dedicated kit.</p> <p>The two tooth corresponding to the arrows (Fig. 1) must be located between the two engine cavities (Fig. 2).</p> <p>Should the correct assembly procedure not be complied with, the tooth could be mispositioned with resulting malfunction of the timing system and system damage as well.</p>



Fig.1




Fig.2

I suggerimenti e/o lo schema di montaggio eventualmente presente sono solo a titolo indicativo. La EXO Automotive Spa non si assume alcuna responsabilità derivante da eventuali errori e/o omissioni e/o modifiche successive apportate al sistema da parte del Costruttore del veicolo. Si consiglia altresì di avvalersi dei dati aggiornati forniti da quest'ultimo.

Recommendations and/or assembly diagram shown here are only for explanation purposes. EXO Automotive Spa doesn't accept any responsibility due to any later error and/or omission and/or modification made by the vehicle manufacturer to the system itself. It is further recommended to use state-of-the-art data supplied by the manufacturer.