

**TECHNICAL**

# BULLETIN



**TECH  
MATE**

Bulletin Ref: TB2a

## AAL1796

This vehicle has a computer driven excitation circuit of the alternator regulator which takes data from the ambient temperature and engine load, a failed temperature sensor or broken wire to the regulator will result in a low charge voltage

Please double check before ordering and fitting.

**TECH  
MATE**

For further information on this or any other issue contact the  
Apec technical team by phone or email at:  
Phone: 01174 288090 Email: [technical@apecautomotive.co.uk](mailto:technical@apecautomotive.co.uk)



**FOLLOW US**  
#TechMate | @TechMateAuto