

TECHNICAL

BULLETIN

**TECH
MATE**

Bulletin Ref: TB31a


Volvo

AAL1939

Common issues for charging problems.

In some cases the ECU/PCM has corrupted software, the application will run on emergency program.

An ECU upgrade via main dealer software may be required.

**TECH
MATE**

For further information on this or any other issue contact the
Apec technical team by phone or email at:
Phone: 01174 288090 Email: technical@apecautomotive.co.uk



FOLLOW US
#TechMate | @TechMateAuto