


TECHNICAL**BULLETIN****TECH
MATE**

Bulletin Ref: TB27a

VAG Ignition Switch**ASM1319**

The ignition switch can be defective causing the starter motor to either keep running resulting in the starter motor burning out prematurely or to not turn at all.

Please double check before ordering and fitting.

**TECH
MATE**

For further information on this or any other issue contact the Apec technical team by phone or email at:
Phone: 01174 288090 Email: technical@apecautomotive.co.uk



FOLLOW US
#TechMate | @TechMateAuto