

Ignition Switch

ASM1722

This vehicle is prone to the ignition start button failing, remaining in the start position causing the starter motor to continually run, this will result in the starter motor premature burning out and also a risk of fire due to overheating.

Please double check the switch before ordering and fitting.









For further information on this or any other issue contact the Apec technical team by phone or email at: Phone: 01174 288090 Email: technical@apecautomotive.co.uk



FOLLOW US #TechMate | @TechMateAuto