



KNOW HOW

TECHNICAL BULLETIN



NAL1118 - Mercedes A Class



© NAPA

A charge issue on the Mercedes A Class CDi is often due to a fault with the engine ECU or the front 'SAM' control unit.

Both of these control units control and monitor the alternator charge output and should be checked before replacing the alternator

Technical Support

Contact our expert technical team
on 03333 136597 or email
NAPATECHNICAL@allianceautomotive.co.uk

**TECH
MATE**

TECHNICAL
PARTNER

TechMate Support

Book a TechMate visit today!
Contact the team on 01174 288090
or email info@techmateteam.co.uk