



KNOW HOW

TECHNICAL BULLETIN




NAL1118 - Mercedes A Class

Bulletin Ref: TB21n

A charging issue on the Mercedes A Class CDi is often due to a fault with the ECU or 'SAM' control unit.

Both of these control units control and monitor the alternator charge output.



Technical Support

Contact our expert technical team
on 03333 136597 or email
NAPATECHNICAL@allianceautomotive.co.uk



TechMate Support

Book a TechMate visit today!
Contact the team on 01174 288090
or email info@techmateteam.co.uk