



# KNOW HOW

## TECHNICAL BULLETIN





**NAL1702**

**Bulletin Ref: TB5n**

**Common issues for charging problems:**

- 1. This unit is controlled by the vehicles ECU which can be defective.**
- 2. A corroded B+ cable from alternator to the battery is also common issue.**



## Technical Support

Contact our expert technical team  
on 03333 136597 or email  
[NAPATECHNICAL@allianceautomotive.co.uk](mailto:NAPATECHNICAL@allianceautomotive.co.uk)



## TechMate Support

Book a TechMate visit today!  
Contact the team on 01174 288090  
or email [info@techmateteam.co.uk](mailto:info@techmateteam.co.uk)