

NAL1712 - 80amp Korean Fuse

Bulletin Ref: TB11n

Before fitting check the 80a PAL type fuse as this fuse can blow causing no charge. (Fig 1.)

Also check for corrosion around and underneath the fuse connections which is common.







Technical Support

Contact our expert technical team on 03333 136597 or email NAPAtechnical@allianceautomotive.co.uk



TECH TechMate Support