



KNOW HOW

TECHNICAL BULLETIN






NAL1747

Bulletin Ref: TB4n

Poor or corroded connections on the rear of the alternator are common creating charging issues, this can also cause the charging light to illuminate when the unit is still charging.

Please double check before ordering and fitting.



Technical Support

Contact our expert technical team
on 03333 136597 or email
NAPATECHNICAL@allianceautomotive.co.uk



TechMate Support

Book a TechMate visit today!
Contact the team on 01174 288090
or email info@techmateteam.co.uk