



KNOW HOW

TECHNICAL BULLETIN




NAL1939 - Volvo

Bulletin Ref: TB31n

Common issues for charging problems.

In some cases the ECU/PCM has corrupted software, the application will run on emergency program.

An ECU upgrade via main dealer software may be required



Technical Support

Contact our expert technical team
on 03333 136597 or email
NAPATECHNICAL@allianceautomotive.co.uk

**TECH
MATE**

TECHNICAL
PARTNER

TechMate Support

Book a TechMate visit today!
Contact the team on 01174 288090
or email info@techmateteam.co.uk