


NSM1265

Bulletin Ref: TB27n

The ignition switch can be defective causing the starter motor to either keep running resulting in the starter motor burning out prematurely or to not turn at all.

Please double check before ordering and fitting.



Technical Support

Contact our expert technical team on 03333 136597 or email NAPAtechnical@allianceautomotive.co.uk



TECH TechMate Support

Book a TechMate visit today! Contact the team on 01174 288090 or email info@techmateteam.co.uk