

NSM1614 - Chevrolet Captiva

Bulletin Ref: TB12n

Vehicles equipped with stop/start system were subject to a main dealer recall in 2017.

'A risk of fire while driving due to thermal damage of the starter cable'

It is vital that this is checked and replaced if the starter motor connection has melted (Fig 1).



Technical Support

Contact our expert technical team on 03333 136597 or email NAPAtechnical@allianceautomotive.co.uk



TECH TechMate Support

Book a TechMate visit today! Contact the team on 01174 288090 or email info@techmateteam.co.uk