



# KNOW HOW


## TECHNICAL BULLETIN



### NSM1722

Bulletin Ref: TB20n

This vehicle is prone to the ignition start button failing, remaining in the start position causing the starter motor to continually run, this will result in the starter motor premature burning out and also a risk of fire due to overheating. Please double check the switch before ordering and fitting.



## Technical Support

Contact our expert technical team  
on 03333 136597 or email  
[NAPATECHNICAL@allianceautomotive.co.uk](mailto:NAPATECHNICAL@allianceautomotive.co.uk)



## TechMate Support

Book a TechMate visit today!  
Contact the team on 01174 288090  
or email [info@techmateteam.co.uk](mailto:info@techmateteam.co.uk)