

CRITICAL INSTRUCTIONS

Application: **Ford Various LCV 2.2LD**

Part Number:
786880-5006S
786880-5012S
786880-5019S
786880-5021S

WHEN FITTING THIS TURBO, IT IS **CRITICAL** THE FOLLOWING INSTRUCTIONS ARE ADHERED TO:

- **Replace Oil Strainer and Oil Feed Pipe**

The sump should be removed and cleaned then a new oil strainer and oil feed pipe fitted.

The oil feed system to the turbocharger has a tendency to become restricted. Most failures of this turbocharger are caused by abrasives/foreign bodies in the oil which collect in the system. Performing the above actions will minimise the risk of the new turbocharger being damaged.



Any questions regarding the above should be directed to the supplier of this unit before commencing any work

