


STEER.



EC3007 & EC3907 ELECTRIC STEERING COLUMN IDENTIFICATION Opel / Vauxhall Corsa C without adjustable column

Care should be taken when identifying the correct Steering Column depending on the Fault Codes.

EC3007

supplied with ECU
required when the fault code is -
C1507 or C1509 - Motor Voltage Fault

EC3907

supplied without ECU
required when the fault code is -
C1500 - Torque Sensor Fault



STEC.10049 18/08/23

