

Product info sh	eet	Robert Bosch	0445010583
Special tools needed?	Yes		
Product specific information			
Programming	No		
Unlocking	No		
Adaption values reset	No		
Bleed	Yes	Activate feed pump by OBD	
adjustment at mounting_1	Yes		
Adjustment at mounting_2		Tightening torques 95 Nm 28 Nm 20 Nm + 45° 20 Nm + 180 °	
Assembly instructions Recommendation: replace fuel filter			
<u>Core charge terms:</u> -externally intact, -no mechanical damage, -not dismantled, -no heavy corrosion.			