

Product info sh	neet	Robert Bosch	0445010685
Special tools needed?	Yes		
Warning: Fuel connections modified pumps. Inlet 13,1		rnpipes can be interchanged by rn 11,1 mm	
Product specific information			
Programming	No		Errer.
		Fix gearwheel when	crankshaft is blocked.
Unlocking	No		
Adaption values reset	No		winn .
Bleed	Yes	Activate feed pump by OBD	
adjustment at mounting_1	No		
adjustment at mounting_2			
		Tightening torque	S
Mounting fuelpump flange		M8 23 Nm, M6 9	9 Nm
High Pressure pipe nuts		25 Nm	
Pump pulley/sprocket		70 Nm	
Camshaft pulley/sprocket		75 Nm	
		Assembly instruction	ons
Recommendation: replace fuel filter			
nedeminentation replace fact filed			
Core charge terms:			
-externally intact,			
-no mechanical damage,			
-not dismantled, -no heavy corrosion.			