

Product info sh	neet	Robert Bosch	0445110239
Special tools needed?	No		
	1		
Product specific information			
Programming	Yes	IMA code (8 characters)	
1000			
Unlocking	No		
Adaption values reset	No		Contraction of the second seco
Bleed	No		
adjustment at mounting_1			
adjustment at mounting_2			
		Tightening torque	es
Injector/ retainingclamp		4 Nm + 65°	
High Pressure pipe nuts		25 Nm	
		A 11 1	
		Assembly instruction	ons
Replace sealing washer			
Core charge terms:			
-externally intact,		D (T D)	
-no mechanical damage,			
-not dismantled, -no heavy corrosion.			