

roduct info sh	eet	Robert Bosch	0445110601
ecial tools needed?	No		

	And I was		
Programming	Yes	IMA code (7 characters)	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
Unlocking	No		
Adaption values reset	No		AAA
Bleed	Yes	ignition on for 30 seconds	
adjustment at mounting_1	No		
adjustment at mounting_2			

Tightening torques					
Injector/ retainingclamp	1: 8 Nm, 2: 26 Nm				
High Pressure pipe nuts	24 Nm				

Assembly instructions

Recommendation: replace fuel filter

Replace sealing washer

Recommendation: use ceramic grease

Recommendation: replace sealing ring

Core charge terms:

- -externally intact,
- -no mechanical damage,
- -not dismantled,
- -no heavy corrosion.





