

## Product info sheet

Robert Bosch

0445116029

Special tools needed?

Yes

Use special tool to turn the coupling nut.



## Product specific information

Programming

Yes

IMA code (7 characters)

Unlocking

No

Adaption values reset

No

Bleed

Yes

primepump activated 30 sec at ignition on

adjustment at mounting\_1

No

adjustment at mounting\_2



## Tightening torques

Injector/ retaining clamp

10 Nm

High Pressure pipe nuts

25 Nm

## Assembly instructions

Replace sealing washer

Recommendation: replace fuel filter

Replace tension bolts

Recommendation: replace sealing ring

### Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.

