

Product info sheet


VDO

A2C59517047

Special tools needed?

Yes

- 1: Block Crankshaft with special tool
- 2: High pressure pump adjustment with pin
- 3: Camshaft adjustment with pin



Product specific information

Programming

No

Unlocking

No

Adaption values reset

No

Bleed


Yes

Activate feed pump by OBD

adjustment at mounting_1

Yes


Respect timingmark pumpsprocket because of pressure-pulse timing



adjustment at mounting_2

Yes

Camshaft with special tools (fixed crankshaft)



Tightening torques

Mounting fuelpump flange

Down 20 Nm + 180 °, upper 20 Nm + 45 °

Pump pulley/sprocket

95 Nm

Assembly instructions

Recommendation: replace fuel filter

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.