

Product info sheet

Denso

DCRI107060

Special tools needed?

No

Attention! Write down the injector ID-code before mounting. Possibly not readable after mounting on the engine.

Product specific information

Programming

Yes

ID code (16 characters)

After programming the calibration codes the procedure for programming the minimum drive pulse needs to be done. This is called "Pilot injection correction" or "zero quantity calibration", depending on type diagnostic tool.

Unlocking

No

Adaption values reset

Yes

perform zero calibration

Bleed

No

adjustment at mounting_1

No

adjustment at mounting_2

--



Tightening torques

Injector/ retaining clamp

6 Nm + 180°

High Pressure pipe nuts

35 Nm

Assembly instructions

Replace tension bolts

Recommendation: replace fuel filter

Replace sealing washer

Replace injector clamp

Core charge terms:

- externally intact,
- no mechanical damage,
- not dismantled,
- no heavy corrosion.