



LuK Service Info

Part Nr. 133 0208 40 – 330mm DGFO

Manufacturer: MASSEY FERGUSON

Model: 1004, 298, 592, 595, 698

Art.-Nr.: 133 0208 40



TB1007

Info: New design / Neues Design / Nouvelle conception / Nuevo diseño / Nuovo disegno / Nuovo segno



633 1120 09 = 133 0208 40 + 333 0052 46

633 1120 10 = 133 0208 40 + 333 0052 46 + 500 0199 40 + 410 0020 40



The Coil spring R clip style housing clutch fitted to Massey Ferguson range of tractors has been replaced by the latest diaphragm and roll pin design.



El embrague de carcasa estilo clip de resorte helicoidal R instalado en la gama de tractores Massey Ferguson ha sido reemplazado por el último diseño de diafragma y pasador antivuelco.



Die Kupplung im Clip-Stil der Spulenfeder R der Massey Ferguson-Traktorenreihe wurde durch das neueste Membran- und Überrollbolzendesign ersetzt.



La frizione con alloggiamento a clip Coil R con molla elicoidale montata sulla gamma di trattori Massey Ferguson è stata sostituita dal più recente design a membrana e a perno.



L'embrayage du boîtier à pince à ressort hélicoïdal R monté sur la gamme de tracteurs Massey Ferguson a été remplacé par le dernier design de diaphragme et de rouleaux.

133 0208 40

Old Design



133 0208 40

New Design



Call : +44 (0) 1432 264264

vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER

REP>XPERT