



LuK Service Info

Part Nr. 228 0218 10 – 280/280MM KGS6

Manufacturer: LANDINI
LANDINI – SOLIS 50

Art.-Nr.: 228 0218 10

Info: 628 3569 09 replaces / ersetzt
/ remplace / sustituye a / sostituisce
228 0218 10



TB1428



628 3569 09 = 228 0218 10 + 328 0587 10



228 0218 10
OE 10022572AB



628 3569 09
OE 10022572AA

Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT