



TB1484

LuK Service Info

Part Nr. 631 3070 19 - 310 SGVO

Manufacturer: **MASSEY FERGUSON**

365, 362, 362N, 372N, 375, 390, 4225, 4235, 4240

Art.-Nr.: 631 3070 19

Info: 631 3070 19 replaces / ersetzt / rem-
place / sustituye a / sostituisce 631 3070 09



631 3070 19 = 131 0051 10 + 331 0157 10



131 0051 10
OE 3701 014 M92



331 0157 10
OE 3701 008 M91

631 3070 19

Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT