



LuK Service Info

Part Nr. 500 1366 10

Manufacturer: MASSEY FERGUSON, LANDINI, UZEL



TB1509

Art.-Nr.: 500 1366 10

Info: 500 1366 10 replaces / ersetzt / rem-
place / sustituye a / sostituisce 500 0885 40



500 0885 40



500 1366 10

Call : +44 (0) 1432 264264
vehiclelifetimesolutions.schaeffler.com

SCHAEFFLER
REP>XPERT