



VO-SB-2320
↔ Ø 21mm
VO-SB-10550
↔ Ø 22mm
VO-SB-13583
↔ Ø 25mm

VO-ES-2314	VO-ES-2315
↔	↔

VO-AX-2313
↔

K150241
↔

VO-LS-2311
↔

VO-SB-2319
↔ ✓ PR 1BA/BB/BC/BJ - 2HD/MF/MG/MH/ML
VO-SB-13719
↔ ✓ PR 0E0 - 1BH/BX - 2MQ/MR/MT/MU

VO-SB-2318
↔

VO-WP-2316 ↔ ✓ Transporter →05/2011, Caravelle →05/2011 PR 1BA/BB/BC/BJ - 2HD/MF/MG/MH/ML ↔ ✓ Multivan →05/2011, California →05/2011	VO-WP-2317 ↔ ✓ Transporter →05/2011, Caravelle →05/2011 PR 1BA/BB/BC/BJ - 2HD/MF/MG/MH/ML ↔ ✓ Multivan →05/2011, California →05/2011
VO-TC-14759 ↔ ✓ Transporter 06/2011→, Caravelle 06/2011→ PR 1BA/BB/BC/BJ - 2HD/MF/MG/MH ↔ ✓ Multivan 06/2011→, California 06/2011→ PR 1BA/BB/BC/BJ - 2HD/MF/MG/MH	VO-TC-14760 ↔ ✓ Transporter 06/2011→, Caravelle 06/2011→ PR 1BA/BB/BC/BJ - 2HD/MF/MG/MH ↔ ✓ Multivan 06/2011→, California 06/2011→ PR 1BA/BB/BC/BJ - 2HD/MF/MG/MH
VO-TC-13775 ↔ ✓ Transporter →05/2011, Caravelle →05/2011 PR 0E0 - 1BH/BX - 2MQ/MR/MT/MU	VO-TC-13776 ↔ ✓ Transporter →05/2011, Caravelle →05/2011 PR 0E0 - 1BH/BX - 2MQ/MR/MT/MU
VO-WP-15443 ↔ ✓ Transporter 06/2011→, Caravelle 06/2011→ PR 0E0 - 1BH/BX - 2MQ/MR/MT/MU ↔ ✓ Multivan 06/2011→, California 06/2011→ PR 0E0 - 1BH/BX - 2MQ/MR/MT/MU	VO-WP-15444 ↔ ✓ Transporter 06/2011→, Caravelle 06/2011→ PR 0E0 - 1BH/BX - 2MQ/MR/MT/MU ↔ ✓ Multivan 06/2011→, California 06/2011→ PR 0E0 - 1BH/BX - 2MQ/MR/MT/MU

VO-BJ-1990
↔
VO-BJ-7050
↔ ✓ 3.2T

VO-SB-10877
↔ Ø 21mm
VO-SB-15445
↔ Ø 21mm
VO-SB-10878
↔ Ø 23mm
VO-SB-15446
↔ Ø 24mm
VO-SB-13288
↔ Ø 27mm
VO-SB-15447
↔ Ø 27mm



VO-SB-13717
↔

VO-SB-13716
↔ X PR 0WR