

HIGHLIGHT EXPERT KITS+ 1.2 PURETECH REPAIR KITS

12001


Information

The 1.2 PureTech engine from Peugeot/ Citroen is operated by a timing belt running in oil. Originally intended to be low-maintenance, it turns out that the belt's coating comes off well before the first change interval and the belt swells.

Loosened timing belt parts get into the oil circuit and clog the suction strainer of the oil pump.

ENGINE DAMAGE IS IMMINENT!

The VAICO EXPERT KITS+ for naturally aspirated and turbo versions of the PureTech engine offer a comprehensive repair solution for this problem. They contain all necessary gaskets, spare parts including an improved timing belt and engine oil to perform a complete change.



* For detailed vehicle information, please refer to the vehicle lists under www.vierol-shop.de. Notes: Temporary offers are only valid while stocks last. All offers remain subject to prior sale. Our general terms and conditions of sale and delivery as well as our warranty conditions apply, which are available for download on our website. All prices are net prices. Errors excepted. Reference numbers and names, with the exception of VIEROL AG, are for comparison only and may not be disclosed in invoices. They are non-binding and no indication of origin. © VIEROL AG

Z