


TSB-303 GM Service Kits

Before fitting this service kit, please check that it is compatible with your flywheel.

FGM115 Service kit: KGM26030








FGM125


Service kit: KGM26031 Vehicle will have a CSC Spacer. This spacer will need to remain on the transmission with the installation of the new kit.







FGM159 Service kit: KGM26031



Does not have CSC Spacer.

Failure to fit the correct kit to the correct flywheel could cause over-stroking of the CSC resulting in a broken CSC and contamination of the clutch components. Fitment of the wrong components is not a warrantable issue.

LEADING BRANDS



For further support, please contact your distributor and/or visit our website.

TREME OUTBACK XCLUTCH

AU site: australianclutch.com.au US site: xclutchusa.com