



# CLUTCHTECH



## TSB-BM02

### Correct Fitment of Driven Plates

*Applies to ClutchPro kits:*  
**KBM23003**  
**KBM23005**  
**KBM22005**

When fitting a KBM23003, KBM23005 or KBM22005 matched kit to BMW 3-series E36, 5-series E28, 5-series E34 or 5-series E39 vehicles the driven plate must be fitted with the two raised lugs on the main plate facing towards the gearbox.

Failure to fit the driven plate correctly will cause the driven plate main plate to foul against the flywheel bolts, resulting in clutch non-release problems in the vehicle.

Please refer to this bulletin when fitting a KBM23003, KBM23005 or KBM22005 matched kit to these vehicles as clutches returned to ClutchPro with damage caused by incorrect driven plate fitment are not acceptable as warranty claims.



#### LEADING BRANDS

**CLUTCHPRO** **CLUTCHPRO**  
COMMERCIAL



[australianclutch.com.au](http://australianclutch.com.au)

1800 CLUTCH (258824)