





TSB-CC03

Pull Type Centralizers

When fitting new centralizers, check the slider parts of the centralizers do not bottom out in the slot in the pressure plate casting. If there is no gap between the slider & the pressure plate casting the clutch will not release.



youtube.com/watch?v=ZVZwXFBYLKs



Scan with a QR app on your smart phone

LEADING BRANDS

CLUTCHPRO **CLUTCHPRO**
RUMKINDAL



australianclutch.com.au

1800 CLUTCH (258824)