



TSB - MD05

Mercedes-Benz Sprinter CDI Differences

Applies to ClutchPro kits: KMB24002 KMB24006

When fitting a KMB24002 or KMB24006 matched kit to Mercedes-Benz Sprinter CDI vehicles manufactured from May 2000 onwards it is essential to ensure that the matched kit has been correctly supplied as the vehicles are fitted with two different dual mass flywheels.

The driven plate is common to both matched kits, but the cover assemblies are not interchangeable. The cover assembly supplied in the KMB24002 kit is specified for fitment to dual mass flywheels with a 8mm recess, while the cover assembly supplied in the KMB24006 kit is specified for fitment to dual mass flywheels with an 11.9mm recess, and the two matched kits are therefore not interchangeable.

The ClutchPro catalogue clearly indicates the dual mass flywheel recess differences and correct matched kit applications for these vehicles and should be followed exactly in order to prevent clutch non-release and slipping problems.













