

TECHNICAL


BULLETIN

**TECH
MATE**

Bulletin Ref: TB8a

AAL1431

The main feed from the battery to alternator is prone to breaking, double check this is in good condition before ordering and fitting.

**TECH
MATE**

For further information on this or any other issue contact the
Apec technical team by phone or email at:
Phone: 01174 288090 Email: technical@apecautomotive.co.uk



FOLLOW US
#TechMate | @TechMateAuto