

# TECHNICAL

# BULLETIN

**TECH  
MATE**



Bulletin Ref: TB11a

## 80amp Korean Fuse

**AAL1712**

Before fitting check the 80a PAL type fuse as this fuse can blow causing no charge. (Fig1.)

Also check for corrosion around and underneath the fuse connections which is common.

**Fig 1.****TECH  
MATE**

For further information on this or any other issue contact the Apec technical team by phone or email at:  
Phone: 01174 288090 Email: [technical@apecautomotive.co.uk](mailto:technical@apecautomotive.co.uk)



**FOLLOW US**  
#TechMate | @TechMateAuto