

TECHNICAL BULLETIN TECH-01-2020

## VW 2.0L - 836026-5005S TURBOCHARGER REPLACEMENT

6<sup>TH</sup> JANUARY 2021





## VW 2.0L - 830323-5006S TURBOCHARGER REPLACEMENT

Dear Customer,

Please note, that production of turbocharger 04L 253 014 L / 830323-5006S was stopped.

As a replacement is available turbocharger 04L 253 014 M / 873767-5001S, which <u>is not a</u> <u>direct service replacement</u> for 830323-5006S.

• There is a different position of the flange for EGR pipe on turbine housing – see below



To replace turbocharger 830323-5006S to be ordered following:

- From Garrett Turbocharger 873767-5001S
- From franchised VW dealer
  - EGR pipe
    - Gaskets
    - Heatshield
    - Necessary fasteners





## VW 2.0L - 830323-5006S TURBOCHARGER REPLACEMENT

## Parts to be ordered from franchised VW dealer

- o EGR pipe
- o Gaskets
- o Heatshield
- Necessary fasteners



Please distribute this information to all in your company who may need it.

Best Regards, IAM Technical Specialist support team. Garrett – Advancing Motion

